




SYMPTOMS	CORRECTIVE ACTION	PARTIAL SERVICE PARTS
1. Poor flush.	A. Clean under bowl rim. B. Plunge bowl, auger trap, auger drain to clear blockage. C. Adjust gap between actuator and plunger arm to approximately 1/8" (3mm). D. Fully open supply stop. E. Clean the screen with a medium to hard bristle brush. Replace the screen if necessary. (Phone 1-800-533-3450 for assistance.) F. Refer to installer/dealer for assistance.	1044434 (LH) 1044435 (RH) Plunger Arm Assy.  78132 Trip Lever Nut  1045276** (LH) 1045277** (RH) Trip Lever
2. No flush.	A. Fully open supply stop. B. Tighten nut (turn counterclockwise to tighten). C. Hook plunger arm over trip arm. D. Clean the screen. (Phone 1-800-533-3450 for assistance.) Replace the screen if necessary. E. Replace inlet components. (Phone 1-800-533-3450 for assistance.)	For service on the Sloan vessel, phone 1-800-533-3450.  84464 Locknut 42398 Washer 42397 Nut 84460 Gasket 51533 Nut 32572 Washer 51743 Washer 51533 Nut 51743 Washer 51624 Screw
3. Bowl water continues to flow or tank fill water will not shut off.	A. Adjust gap between actuator and plunger arm to approximately 1/8" (3mm). B. Repair or replace plunger arm (refer to installer/dealer for assistance). C. Replace the lower supply group.	**Finish/color code required.
For additional assistance, also refer to Flushmate® Owner's Service Manual supplied with tank.		
<b>WARNING:</b> Use only genuine Kohler parts as shown to avoid property damage.		
If unable to correct the problem, contact Customer Service: 1-800-4-KOHLER (USA), 1-800-964-5590 (Canada), or www.kohler.com.		