



MATERIAL SAFETY DATA SHEET

LEVEL-RIGHT PLUS, FS-10 AND FEATHEREDGE

MSDS No. 100B

Page 1 of 3

Maxxon® Corporation
920 Hamel Road, PO Box 253
Hamel, MN 55340

Issue date: January, 2006

Revision date:

SECTION I PRODUCT IDENTIFICATION

Product Name: Level-Right® Plus
Level-Right® FS-10
Level-Right® Featheredge
Product Number: 43A-14256
Product Use: Floor Underlayment
Chemical Emergency or information, call: Maxxon Corporation, 763-478-9600 (Q.A. Dept.)
or Chem-Trec at 1-800-424-9300

SECTION II HAZARDOUS INGREDIENTS

Hazardous components (Specific chemical identity: <u>common name(s)</u>)	<u>OSHA PEL</u>	<u>ACGIH TLV</u>	<u>Other Limits Recommended</u>
Sodium Naphthalene	N/A	N/A	
Sulfonate	N/A	N/A	
Glassy Calcium Silicates			
	3Ca O SiO ₂		
	2Ca O SiO ₃		
	3Ca O Al ₂ O ₃		
	S		
Free silica	SiO ₂		
Alloys	Al ₂ O ₃		
Metallic coating	Fe ₂ O ₃		

SECTION III PHYSICAL DATA

BOILING POINT: N/A
VAPOR PRESSURE: N/A
VAPOR DENSITY: N/A
SPECIFIC GRAVITY (H₂O): 2.5



MATERIAL SAFETY DATA SHEET

LEVEL-RIGHT PLUS, FS-10 AND FEATHEREDGE

MSDS No. 100B
Page 2 of 3

MELTING POINT:	N/A
EVAPORATION RATE:	N/A
SOLUBILITY IN WATER:	(.08 - .09) %
APPEARANCE AND ODOR:	grey, odorless

SECTION IV FIRE AND EXPLOSION DATA

FLASH POINT:	N/A
FLAMMABLE LIMITS:	N/A
HAZARDOUS COMBUSTION PRODUCTS:	None
AUTOIGNITION TEMPERATURE:	N/A
FIRE EXTINGUISHING MEDIA:	N/A

SECTION V REACTIVITY DATA

STABILITY:	Stable
INCOMPATIBILITY (MATERIALS TO AVOID):	None
CONDITIONS TO AVOID:	None
HAZARDOUS DECOMPOSITION PRODUCTS:	None
HAZARDOUS POLYMERIZATION:	Will not occur

SECTION VI HEALTH HAZARD DATA

Inhalation of respirable crystalline silica dust over a long period of time has shown to cause pneumoconiosis (silicosis).

Signs and Symptoms of Exposure: Wet material can dry skin and cause alkali burns. Dust can irritate eyes and upper respiratory tract if inhaled. Ingestion may result in obstruction, get medical attention.



MATERIAL SAFETY DATA SHEET LEVEL-RIGHT PLUS, FS-10 AND FEATHEREDGE

MSDS No. 100B
Page 3 of 3

SECTION VII EXPOSURE CONTROL/PERSON PROTECTION

Engineering Controls: Provide local exhaust as necessary to meet OSHA requirements for dust exposure. Use wet methods, if appropriate, to reduce generation of dust.

Skin Protection: Protective gloves may be desirable to prevent drying or irritation of hands.

Respiratory Protection: Wear NIOSH/OSHA approved respirator when permissible exposure limits to dust may be exceeded.

Eye Protection: Recommend eye goggles or safety glasses for nuisance dust.

SECTION VIII HANDLING AND STORAGE

SPILLAGE: Use dry clean up method that does not disperse dust into the air. Do not breathe dust, avoid contact with eyes.

WASTE DISPOSAL: Material can be disposed of as common waste.

HANDLING AND STORAGE: Keep material dry. High humidity or moisture may cause premature hardening of material.