

Square and Round Bases

Tools Required

- Cordless Drill
- #2 Phillips Head Bit
- Tape Measure

Hardware Required

- #8 x 1" Phillips Panhead Screw

Installation

Important:

- For Square Bases, bottom of Base, rather than mounting plate, must be squared with Worksurface.
- Worksurfaces and Bases should be handled with 2 people
- 1. With Worksurface face-down on clean flat surface, lay Base on Worksurface as shown in Figures A and B.
- 2. Center column of Base on Worksurface and fasten with #8 x 1" Phillips Panhead Screws (12 per Base). (Figures A and B)
- 3. For Gas-adjustable Bases, attach Lever with #8 x 1" Phillips Panhead Screws (4 per Lever), ensuring edge of Lever is flush and square to edge of Worksurface. (Figure C)

Tips

1. For tables with Gas-adjustable Bases, Base should be in lowest position prior to lifting table right-side-up.

Figure A




Figure B




Figure C

