



Arc-Com Fabrics, Inc.
33 Ramland South
Orangeburg, NY 10962

Tel (845) 365-1100 (800) 223-5466
Fax (845) 365-1285 www.arc-com.com

Cleaning Instructions:

Wash Cycle:

Process as ordinary colored fabric, temperature not to exceed 160°F. **Use synthetic detergent.** Add fabric softener to the last rinse.

Extracting Cycle:

Fabric requires no more than 2-4 minutes extracting, depending on the size of the load and equipment used.

Drying Cycle:

Do no overload dryer. Tumble dry 3-5 minutes on synthetic cycle (110°F). As with all polyester fabrics, excessive heat will detract from the permanent press characteristics of this fabric.

Finishing:

If the fabric is folded upon completion of drying cycle, no finishing is required. Occasional light touch-up with hand iron (275°F maximum), or Flat Bed Press with covered head may be desired for smoother seams. **Use cover cloth between fabric and iron or pressing head. Avoid prolonged contact with head.**

Do not use caustic soap or bleach.
Do not put through mangle.