#### 1

# Modesty Surround

## **Tools Required**

- Cordless Drill
- #2 Phillips head bit

## Hardware Included


- #8 x 5/8" panhead screws
- L brackets
- Double side adhesive tape

#### Installation

- 1. These components are non-handed and can be configured as a left or right surround. (Figure A)
- 2. Fasten short end panels to inside of long back panel with brackets and screws provided. (Figure B)
- 3. To install, place worksurface on clean soft surface underside facing up. Fasten surround to worksurface with brackets and screws provided. (Figure C)
- 4. Carefully turn the worksurface upright and place it on the benching worksurface in its desired position mark this location. Lift the surround and remove the film backer from the double-sided adhesive tape. Adhere the surround to the marked location on the benching worksurface.

**CAUTION:** The tape is a very strong adhesive and bonds instantly to any surface it is applied to.

Figure A
Right Shown






Figure C





Figure D



Kimball Office