



Arc-Com Fabrics, Inc.  
33 Ramland South  
Orangeburg, NY 10962

Tel (845) 365-1100 (800) 223-5466  
Fax (845) 365-1285 [www.arc-com.com](http://www.arc-com.com)

## Cleaning Instructions: Prism

### Cleaning Code : WS / Bleach Cleanable

Water based cleaning agents and foam may be used for cleaning. This fabric may also be cleaned with mild, water-free solvents.

Cleaning by a professional service is recommended.

May be cleaned with bleach following the proper ratio of 90% water : 10% bleach.

All cleaning should allow for a 10-minute maximum sit time and then **MUST BE PROMPTLY AND PROPERLY RINSED.**