Homogeneous & Inlaid Sheet

MEDINTONE™ | MEDINTECH® | MEDLEY™ | ROYAL* | SOLID* | POSSIBILITIES® Petit Point™ | Connection CORLON®

*Canadian exclusive

The above products are manufactured with a protective urethane finish that provides improved maintenance characteristics and maintenance options for the end-user.

For Best Results:

- Wipe a narrow band of a protective finish on heat-welded seams. When using one of the No-Polish Options, it may be necessary to periodically recoat the welded seam.
- When performing wet maintenance, always use proper signage and prohibit traffic until the floor is completely dry.
- Do not wet wash, machine scrub, or strip the floor for at least 4 days after installation. This is to prevent excess moisture from interfering with the adhesive bond and/or seam treatments.
- Do not use excessive amounts of liquid during maintenance.
- Do not use brown or black pads, equivalent brushes or stiff-bristled, highly-abrasive brushes on Armstrong® resilient flooring.
- If it becomes necessary to move any heavy fixtures or appliances over the flooring on casters or dollies, the flooring should be protected with 1/4" or thicker plywood, hardboard or other underlayment panels. If other on-site work is continuing, consider using a protective covering such as plain, undyed Kraft paper to guard against damage to the new floor.

A. Initial Maintenance and Preparation for Commercial Traffic





- Sweep, dust mop or vacuum the floor thoroughly to remove all loose dust, dirt, grit and debris.
- 2. Remove any dried adhesive residue with a clean, white cloth dampened with mineral spirits, carefully following the warnings on the container.





3. Damp mop the floor with a properly diluted neutral (pH 6 to 8) detergent solution such as Armstrong® S-485 Commercial Floor Cleaner.





4. If necessary, machine scrub the floor with a properly diluted neutral detergent solution such as Armstrong S-485 Commercial Floor Cleaner and the appropriate scrubbing pad (3M red or equal for light scrub, 3M blue or equal for a deep scrub) or equivalent brushes. NOTE: If the floor will be maintained with the Polish Option, the floor must be scrubbed with a floor machine fitted with a red scrubbing pad (3M red or equal).



5. Thoroughly rinse the entire floor with fresh, clean water. Remove rinse water and allow the floor to dry completely.

Having completed Steps 1-5 above, choose a maintenance option based on your evaluation of the factors listed under "How to Determine Your Maintenance Program" (see page 12) and proceed as directed below.

6. Maintenance options:



 Polish Option – apply 3 to 5 coats of high-quality commercial floor polish, such as Armstrong® S-480 Commercial Floor Polish. In areas where the flooring will be exposed to heavy traffic and/or staining agents, the application of a stain resistant sealer (such as Armstrong® S-495 Commercial Floor Sealer) prior to the application of polish is recommended.



• **Spray Buff Option** – spray buff using a rotary machine (175 to 600 rpm) with the appropriate pad and spray buff solution.



• Dry Buff Option – dry buff (maximum 1,500 rpm) with the appropriate pad until the desired luster is achieved. If a higher gloss is desired, the application of a suitable floor finish is recommended.

B. Daily/Regular Maintenance





1. Sweep, dust mop or vacuum the floor daily to remove dust, dirt, grit and debris that can damage the floor and become ground into the surface.



2. Spot mop as needed. Any spills should be cleaned up immediately.





3. Damp mopping of the floor should be performed on a regular or daily basis, depending upon traffic and soil levels in the area. Use a properly diluted neutral detergent solution, such as Armstrong S-485 Commercial Floor Cleaner.

C. Periodic Maintenance







 When needed, machine scrub the floor with a properly diluted neutral detergent solution such as Armstrong S-485 Commercial Floor Cleaner and the appropriate scrubbing pad (3M red or equal for light scrub, 3M blue or equal for a deep scrub) or equivalent brush.



2. Thoroughly rinse the entire floor with fresh, clean water. Remove rinse water and allow the floor to dry completely.







- 3. Based on the selected maintenance option above, do one of the following:
 - If maintaining with the **Polish Option** and a sufficient base (3 to 5 coats) of polish remains, buff, spray-buff or burnish to restore gloss. If needed, additional coats of floor polish may be applied at this time.



• If maintaining with the **Spray Buff Option**, spray buff using a rotary machine (175 to 600 rpm) with the appropriate pad and spray buff solution. This may be followed by dry buffing with a white pad.



• If maintaining with the **Dry Buff Option**, dry buff (maximum 1,500 rpm) with the appropriate pad until the desired luster is achieved. **If a higher gloss is desired, the application of a suitable floor finish is recommended.**

D. Restorative Maintenance - Stripping





 Mix stripping solution to the appropriate dilution, depending on floor finish build-up. Blockade areas to be stripped. Apply liberal amounts of solution uniformly to the floor with a mop. Let stripping solution soak for the appropriate amount of time recommended by the stripper manufacturer. Keep areas to be stripped wet. Rewet if necessary.





 Machine scrub the floor (300 rpm or less) with a scrubbing pad (3M blue or equal) or equivalent scrub brush to break up the polish film. Do not allow stripping solution to dry on the floor.





3. Remove dirty stripping solution with a wet vacuum or mop. **TIP: Drizzling** fresh, clean rinse water onto the dirty stripping solution will assist with a more thorough removal.



4. Thoroughly rinse the entire floor with fresh, clean water. Remove rinse water and allow the floor to dry completely.



5. Based on the selected maintenance option above, do one of the following:





• If maintaining with the **Spray Buff Option**, spray buff using a rotary machine (175 to 600 rpm) with the appropriate pad and spray buff solution. This may be followed by dry buffing with a white pad.



• If maintaining with the **Dry Buff Option**, dry buff (maximum 1,500 rpm) with the appropriate pad until the desired luster is achieved. **If a higher gloss is desired, the application of a suitable floor finish is recommended.**