

SAFETY DATA SHEET Issue No: 11 Date: 20 September 2013

### . IDENTIFICATION OF THE SUBSTANCE/PREPARATION AND THE COMPANY

PRODUCT NAME: Altro Safety Flooring

Altro Walkway 20 / PLus (VM20 / VM20SD / VMI20)

Altro Designer 25 (D25) Altro Classic 25 (X25) Altro Atlas 40 (X40) Altro Impressionist II (IP20)

Altro Timbersafe II (TS20)

Altro Suprema II (SU20/SUI20) Altro Wood Safety

PRODUCT TYPE/USE: Vinyl Sheet Flooring
EMERGENCY TEL NOS: 01462 480480
01462 489269
SUPPLIER: ALTRO FLOORS
WORKS ROAD

LETCHWORTH GARDEN CITY

HERTS, SG6 1NW 01462 480480

 TELEPHONE:
 01462 480480

 FAX:
 01462 480010

 CONTACT PERSON:
 Barry Hall

MANUFACTURER: Please contact Altro for details.

Altro Maxis 25 (MXI25 / MXD25) Altro Stronghold 20/30 (K20/K30)

Altro Marine 20 (T20)

Altro XpressLay / Plus (XL22 / XLI22)

Altro ContraX (CX20) Altro Mirica (MC20)

Altro Aquarius (AQ20/AQI20)

Altro Uno (AU20) Altro Unity (UB25/UBI25

#### 2. COMPOSITION/INFORMATION ON INGREDIENTS

HAZARDOUS INGREDIENTS	CAS NO:	CONTENT	HEALTH	RISK PHRASES
NON-HAZARDOUS				

#### 3. HAZARDS IDENTIFICATION

**INHALATION:** No risk under normal circumstances, but in a major fire PVC may burn; Hydrogen chloride (HCL) is formed. This

will irritate the inhalation system. HCL forms Hydrochloric acid when in contact with water or moisture.

**SKIN CONTACT:** No risk under normal circumstances.

**EYE CONTACT:** As for inhalation. If HCL is formed it can react with the moisture in the eyes to form Hydrochloric acid. This will

cause severe irritation to the eyes.

**INGESTION:** May cause choking otherwise it is non-hazardous.

**GENERAL COMMENTS:** If flooring is not maintained as recommended by Altro the safety properties may be affected.

# 4. FIRST AID MEASURES

**INHALATION:** If PVC flooring is ignited move the exposed person to fresh air. If breathing is difficult, properly trained personnel

may assist affected person by administering 100% oxygen. Keep the affected person warm and at rest. Get

prompt medical attention.

SKIN CONTACT: Non-hazardous

**EYE CONTACT:** If PVC flooring is ignited and Hydrochloric acid has formed from the moisture in the eyes; promptly wash eyes

with plenty of water while lifting the eye lids. Continue to rinse for at least 15minutes and get medical attention.

If stuck in throat remove by any means possible. Seek medical attention immediately if choking persists.

### 5. FIRE FIGHTING MEASURES

INGESTION:

**EXTINGUISHING MEDIA:** Water spray, fog or mist. Foam. Carbon dioxide (CO2).

SPECIAL FIRE FIGHTING PROCEDURES: Self extinguishing but will burn in the presence of flames. HCL is formed, use protection mask for acidic gases.

HAZARDOUS COMBUSTION PRODUCTS: Fire creates: Hydrogen chloride (HCL).

## 6. ACCIDENTAL RELEASE MEASURES

STEPS TO BE TAKEN IF PRODUCT IS

Non-Applicable

RELEASED OR SPILT:

### 7. HANDLING AND STORAGE

**USEAGE PRECAUTIONS:**No special precautions are required. Ensure all handling is carried out according to the Kinetic method of lifting. **STORAGE PRECAUTIONS:**Rolls of material should be stored in the vertical position and must be restrained using a safety chain or rope.

Store in a clean, dry area. Full rolls weigh in excess of 100Kg.

STORAGE CRITERIA: Non hazardous material storage.

Altro Safety Flooring Page 1 of 2



SAFETY DATA SHEET Issue No: 11 Date: 20 September 2013

## **EXPOSURE CONTROLS / PERSONAL PROTECTION**

INGREDIENT NAME CAS NO: STD LTEL STEL mg/m3 ppm mg/m3 ppm NON-HAZARDOUS

PROTECTIVE EQUIPMENT: None Required

**HYGENIC WORK PRACTICES:** Maintain the flooring as recommended by Altro.

PHYSICAL AND CHEMICAL PROPERTIES

APPEARANCE: Up to 2m wide rolls of flooring

**BOILING POINT (`c, interval):** Not applicable COLOUR: DENSITY/SPECIFIC GRAVITY (g/ml): Various Approximately 1.28

ODOUR/TASTE: Typical - low odour VISCOSITY:

**SOLUBILITY DESCRIPTION:** OTHER PHYSICAL DATA: VOC data available from Altro Not applicable

STABILITY AND REACTIVITY 10.

STABILITY: Stable. Avoid: Flame contact

MATERIALS TO AVOID:

HAZARDOUS DECOMPOSITION PRODUCTS: Toxic gases/vapours/fumes of: Hydrogen chloride (HCL).

11. TOXICOLOGICAL INFORMATION

11. TOXICOLOGICAL INFORMATION (SYMPTOMS)

**OTHER HEALTH EFFECTS:** None.

**HEALTH WARNINGS:** Can cause irritation from the HCL formed when PVC flooring is burning.

**ROUTE OF ENTRY:** NON-APPLICABLE **TARGET ORGANS:** NON-APPLICABLE MEDICAL SYMPTOMS: NON-APPLICABLE

12. ECOLOGICAL INFORMATION

**BIO ACCUMULATION:** Very low potential for bioaccumulation.

**DEGRADABILITY:** Very slowly biodegradable. **ACUTE FISH TOXICITY:** Not toxic to aquatic organisms.

**DISPOSAL CONSIDERATIONS** 

**DISPOSAL METHOD:** Landfill in accordance with local regulations.

TRANSPORT INFORMATION

LABEL FOR CONVEYANCE: None Required

REGULATORY INFORMATION

LABEL FOR SUPPLY: None required. RISK PHRASES: Not applicable. **SAFETY PHRASES:** Not applicable.

16. OTHER INFORMATION

**GENERAL INFORMATION:** Joints to be welded with PVC weldrod and hot air gun. Provide good ventilation when welding. Observe PPE

regulations. 20/09/2013

**REVISION DATE:** SDS INITIALLY GENERATED: 24/4/96

The information provided in this safety data sheet is correct to the best of our knowledge, information and belief at the date of its publication. The information given is designed only as guidance for safe handling, use, processing, storage, transportation, disposal and release, and is not to be considered a warranty or quality specification. The information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process unless specified in the text.

Altro Safety Flooring Page 2 of 2