

## Trek - Windows

---

### Care 1

#### MAINTENANCE INSTRUCTIONS FOR WINDOWS

This fabric is machine washable, and can be washed by using the following basic instructions:

- Wash warm (105°F - 120°F) on delicate / permanent press cycle.
- Use only non-chlorine bleach when necessary.
- Line dry immediately after machine washing.
- If desired, you can press with commercial steam iron or flat bed press at low temperatures suitable for synthetic materials
- Dry cleaning is permissible. Use only commercial dry cleaners.